


9
8
7
6
5
4
3
2
1
0



In case you should carry out an update, make sure that the interface card RS232 for channel 1 has been mounted !

If necessary, replace the mounted RS422-card by the RS232-card.
Please do not forget to remount the correct card after the update has been carried out!

geändert:	Zeichnungs-Nr.: PL10141	Versions-Nr.: 002	Blatt 1 / 1
	erstellt: 16.03.2005 jr	Ersatz für:	Artikel-Nr.
	bearbeitet: 18.04.2005 jr	gültig ab:	
	freigegeben:	gültig bis:	
Update-cable serial RS232			
FÖRSTER TECHNIK			