



- ① - remove blind plug
 - mount screwed cable gland
 - insert line of identification 1 and 2
 - mount shield according to diagram
 (cut off standard shield connection)



connection identification feeding box 1/2

				connection micro-identification (Calfscan) 1/2 to SA 2000 with double priority control		Förster Technik GmbH		Zeichnungs-Nr. plan408a		Blatt 1	
						gezeichnet		Datum 15.06.00		von 1 Blätter	
Änderung				Ind. Datum Name		Name Hensler		Versions-Nr. 2			