



②
- plug-in plug
- connect wire

①
- remove blind plug
- mount screwed cable gland
- insert line of remote control 1/2

flange for external connections

connection
cable remote control box
feeding box 1/2

				connection cable remote control box 1/2 to SA 2000 with double priority control		Förster Technik GmbH		Zeichnungs-Nr. plan410a		Blatt 1	
						gezeichnet		Datum 14.06.00		Versions-Nr. 2	
Änderung				Ind. Datum Name		Name Hensler				von 1 Blätter	