


=LT1 power unit SA2 Plus



in case of problems with the electrode in the mixer jar  
(the liquid in the mixer jar overflows resp. there is lack of water),  
install an additional bonding point!

				Improvement of Bonding on SA2 Plus		Förster Technik GmbH		Zeichnungs-Nr. SK10071		Blatt	
						gezeichnet		Datum 28.02.2002		Gültig ab: 28.02.2002	
Änderung				Ind. Datum Name		Name		Gültig bis:		von Blätter	